



GARY R. HERBERT  
Governor

GREGORY S. BELL  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

October 5, 2010

Reviewed: PPS

<b>Mine Name:</b> Fox Clay	<b>Permit Number:</b> S/049/0077
<b>Operator Name:</b> Interpace Holdings, LLC	<b>Inspection Date:</b> Sept. 20, 2010
<b>Inspector(s):</b> Lynn Kunzler	<b>Time:</b> 1:20 pm
<b>Other Participants:</b> None	<b>Mine Status:</b> Proposed

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

Routine inspection while in the area.

#### Inspection Summary:

The Division received the Notice for this operation June 17, 2010. The original notice had approximately 2 acres proposed that overlapped on Interstate Brick's Snow White mine. Rather than revising the area that would be disturbed, the operator agreed to wait for Interstate Brick to request a surety release for the overlap area. The request was made, and the inspection to determine whether success standards were achieved for release was done this same day. The area can be released, which will now allow the Division to proceed with permitting of the Fox Clay mine as originally proposed.

At this time, there is no disturbance on site that has not been successfully reclaimed. The area is dominated by a sagebrush vegetation community with minor amounts of pinyon/juniper woodland on the southern side.

Photos were taken to document site conditions.

#### Conclusions and Recommendations:

The proposed operations can now be permitted, pending Interpace submitting the required reclamation surety. Continue to monitor the site when in the area.

Inspector's Signature

[Signature]

cc: Interpace Holdings, LLC.

O:\M049-Utah\S0490077-FoxClay\inspections\insp-09202010.doc